St. Croix Sensory, Inc.

Odor Evaluation Report

Client: SPF-USA

Project:

Report No.: **814201**

Evaluation Date: 05/21/08

			ASTM E679 & EN13725		ASTM E544	PERSISTENCY	CHARACTERIZATION		
#	Field No.	Sample Description	Detection Threshold	Recognition Threshold	Intensity	Dose-Response Slope	Hedonic Tone	Principal Odor Descriptors	**Comments**
1	1	Roof Inlet	6,200	3,300					
2	2	North Rocks	180	110					
3	3	Roof Inlet	3,500	2,300					
4	4	North Rocks	190	100					
5	5	Roof Inlet	5,800	3,100					
6	6	South Rocks	210	120					
7	7	Roof Inlet	8,400	4,600					
8	8	South Rocks	180	120					
9									
10									